

# Managing OIP Transformer Bushings on Eskom & NTCSA's Transformers: Standardization and Replacement Challenges

Khayakazi Dioka, Eskom NTCSA

---

## 92<sup>nd</sup> International Conference of Doble Clients





# Introduction to Bushings

© Doble Engineering

# Introduction to Bushings



1

A bushing is a crucial component in transformers, allowing conductors to pass through grounded barriers while providing insulation between high-voltage windings and the transformer tank.

2

Bushings are critical for the safe operation of transformers, ensuring that the electrical connections do not pose a risk to the surrounding environment or personnel.

3

Bushings are designed to last 20–30 years, with transformers having a lifespan of around 40 years, meaning bushings typically require replacement at least once during the transformer's service life.



# Eskom/NTCSA Bushing Journey

© Doble Engineering

# Eskom/NTCSA Bushing Journey




## • Oil-Impregnated Paper (OIP) Bushings

- Historically used in Eskom and NTCSA transformers.
- Subject to performance issues and failures over time, leading to increased maintenance and replacement needs.

## • Introduction of Resin-Impregnated Paper (RIP) Bushings (2007)

- Transitioned to RIP technology for better reliability, safety, and reduced fire risk.
- RIP bushings have superior fail-safe features, making them a more secure option for transformer networks.



## • Standardization:



- Eskom standardized its transformer fleet, promoting compatibility and better management of spare parts, including bushings.

# Managing OIP Bushing Fleet 2007-2016



## Replacement of Defective OIP Bushings:

- Known defective OIP bushings were replaced through national projects, particularly for 400kV, and 275kV transformers.
- Other bushings, e.g., 132kV, 88kV, were modified to extend their service life.



## Managed through different technical instructions – Specific bushing type

- Test point modifications – screw on cap seizes and cannot be removed – fitting lock-nut and dust cap
- Inspection and test



# Managing OIP Bushing Fleet 2016 to Date



- All OIP type bushings >20 years in service, with no test records  $\leq 36$  months retest and analyse.
- Routine sampling every 3 years.
- Only use serviceable OIP bushings in stores under emergencies.
- No replenishment of stock by OIP bushings.



| Test                              | Findings  | Action  |
|-----------------------------------|---|---|
| 1) Visual Inspection              | Discoloration of gauge glass ,no oil level and oil leak is evident from bushing compartment | Remove and scrap                                      |
| 1) Tan Delta and Capacitance Test | Tan delta < 0.5   | Keep in service if no leaks or thermal issues.        |
|                                   | $0.5 \leq \tan \text{ delta} < 0.7$   | Keep in service, test yearly and plan for replacement |
|                                   | Tan delta >0.7%   | Immediately remove from service and scrap it          |
| 1) Infrared scanning              | Overheating detected when comparing phases  | Investigate, repair or replace.                       |



# Eskom/NTCSA Bushings Health Appraisal

© Doble Engineering

# Bushings Health Appraisal – 2020 Results



## Bushing Condition Assessment:


| Tan delta Values | Condition     | Recommended Action                                    |
|------------------|---------------|---|
| <0.5%            | Good          | Normal Maintenance                                    |
| 0.5% - 0.7%      | Deteriorating | Keep in service, test yearly and plan for replacement |
| ≥0.7%            | Deteriorated  | Replace Immediately                                   |

## Testing and Results Analysis:

| Grid     | Tested bushings (%) | Bushings for replacement (no.) | Bushings requiring increased monitoring frequency (no.) |
|----------|---------------------|--------------------------------|---|
| Region 1 | 88%                 | 1                              | 2   |
| Region 2 | 33%                 | 7                              | 27  |
| Region 3 | 75%                 | 0                              | 24  |
| Region 4 | 86%                 | 0                              | 22  |
| Region 5 | 91%                 | 0                              | 55  |
| Region 6 | 32%                 | 1                              | 9   |
| Region 7 | 76%                 | 6                              | 57  |
| Region 8 | 81%                 | 4                              | 33  |
| Region 9 | 85%                 | 4                              | 42  |

# Challenges – Data and Testing

- **Missing data** - 54% of the OIP bushings in service test results were available for analyses.
- **Unknown bushings** – nameplate information
- **No test tap** – no test results, bushings removed for testing.
- **Incorrect results** - Environmental Factors (Dust, dirt, atmospheric moisture)



# Challenges - Standardized Bushings Replacing Non-Standardized Bushings


Standard network voltages with different bushing sizes, e.g., 132kV 1250A bushing

|                                | Bushing A1  | Bushing A2 | Bushings A3 | Bushing A4 | Standardized Bushing |
|--------------------------------|-------------|------------|-------------|------------|----------------------|
| <b>Oil Side Length (mm)</b>    | 580         | 740        | 940         | 1130       | 660                  |
| <b>Flange diameter(mm)</b>     | 335         | 335        | 335         | 520        | 290                  |
| <b>PCD (mm)</b>                | 290         | 290        | 290         | 470        | 250                  |
| <b>Fixing bolts (no. x mm)</b> | 12 x 16 (Ø) | 12 x 16(Ø) | 12 x 16(Ø)  | 12 x 20(Ø) | 8 x 16(Ø)            |
| <b>CT extension length</b>     | 150         | 300        | 480         | 600        | 300                  |
| <b>CT Ext diameter</b>         | 200         | 160        | 190         | 325        | 160                  |

# Challenges - Standardized Bushings Replacing Non-Standardized Bushings

Typical design modifications include;

- manufacturing of adaptor flanges to be rewelded on existing flanges
- manufacturing new solid rods (conductors), or machining replacement conductor to required lengths
- cutting of exit leads to be connected into shortened conductor
- manufacturing an adaptor turret where the replacement bushing is longer than an existing bushing



# Ultimate Bushing Replacement Challenges to Transformer Fleet



- **Prolonged outages** – testing, modifications, and full commissioning (full drain/partial drain).
- **Intrusive work management** – quality issues, human error effect e.g., transformer severe incident
- **Quick depletion of inventory** – fail one, replace three, slow procurement process.
- **Skill availability** – testing and installation



# Highlights/Learnings

- Data management - unavailability of records > retesting
- The importance of standardization on components for compatibility and strategic spares management
- Clearly defined maintenance scope of work/method statements, instruction documents, etc.
- Skills development (local Doble trainings and workshops)



Thank you.

© Doble Engineering

